## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

## EXPRESS MAIL NO. EV220475369US INTERFACE STRUCTURE FOR A SHOWER SURROUND Applicant: Sisk; Attorney docket 60137-247



EXPRESS MAIL NO. EV220475369US INTERFACE STRUCTURE FOR A SHOWER SURROUND Applicant: Sisk; Attorney docket 60137-247

2/6




Fig ZA

Fig ZB






Fig 3

EXPRESS MAIL NO. EV220475369US
INTERFACE STRUCTURE FOR A SHOWER SURROUND





Figs




Fig 6